

Vulnerability of Ethernet communication in TOYOPUC products
pointed out by an external organization

1. Introduction

We will inform you of a content pointed out to us by an external organization regarding and how to deal with it on this document.

Please check contents and implement workaround measures as necessary.

2. Content pointed out

If Ethernet communication of the affected product is left in an open state by an attacker, Ethernet communications cannot be established with other devices, depending on the settings of the link parameters.

3. Affected products

The following products are affected by this vulnerability when a link parameter is set to "Ethernet" or "Ethernet (32ports)" and used as "TCP Destination Non-Specified Passive Open".

| Affected product | Type | Affected version |
|------------------|----------|------------------|
| PC10G-CPU | TCC-6353 | All |
| PC10GE | TCC-6464 | All |
| PC10P | TCC-6372 | All |
| PC10P-DP | TCC-6726 | All |
| PC10P-DP-IO | TCC-6752 | All |
| PC10B-P | TCC-6373 | All |
| PC10B | TCC-1021 | All |
| PC10B-E/C | TCU-6521 | All |
| PC10E | TCC-4737 | All |
| Plus CPU | TCC-6740 | All |
| Plus EX | TCU-6741 | All |
| Plus EX2 | TCU-6858 | All |
| Plus EFR | TCU-6743 | All |
| Plus EFR2 | TCU-6859 | All |
| Plus 2P-EFR | TCU-6929 | All |
| Plus BUS-EX | TCU-6900 | All |
| FL/ET-T-V2H | THU-6289 | All |
| 2PORT-EFR | THU-6404 | All |

4. Detail content pointed out

In Ethernet communication of TOYOPUC products, Ethernet communication cannot be established with a device that should be connected in the following cases.

- If a connection is not closed correctly when the connection is disconnected
- If a connection is connected and left in that state

Reset/start or power-on of the PLC is required for recovery.

The CVSS V3.0 base score is 7.5.

The CVSS V3.0 temporal score is 7.2.

[CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H/E:H/RL:O/RC:C](https://www.first.org/cvss/CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H/E:H/RL:O/RC:C)

“Reference”

Please refer to the following URL about CVSS score.

<https://www.first.org/cvss/>

5. Threat by this pointed out content

When a connection is not closed correctly by an attacker in Ethernet communication of TOYOPUC products, after that, Ethernet communication cannot be established with a device that should be connected.

6. Workarounds and mitigations

If you want to mitigate a threat, please refer to the following "Workaround" to change settings.

Regardless of this matter, we recommend that you make appropriate security settings such as firewalls and manage a network to prevent suspicious devices from connecting to the network to which a product is connected.

“Workaround”

Please set “Non-Reception timer” to "Enable" from in various timer settings of a detailed setting of a link parameter "Ethernet" or "Ethernet (32Port)".

After setting the link parameter, **please connect a computer and a PLC with a USB cable** and write the link parameter.

After writing is completed, perform a reset/start or power-on again.

After reset/start or power-on, the parameter changes take effect.

When Non-Reception timer is enabled, the connection that was not closed correctly can be reset after the set time has elapsed. And a connection can communicate with a device that should be connected.

For details on the settings, refer to the User's Manual of each device.

7. History

April 15th, 2021 This information has been released.

8. Contact us

For inquiries regarding this content, please contact the following e-mail address.

E-mail: JJP_PSIRT@jtekt.co.jp